

**UNIGRAPHICS**

---

***MULTI-AXIS MACHINING  
WORKBOOK  
November 2002  
MT11050 – Unigraphics NX***

**EDS Inc.**

# Proprietary & Restricted Rights Notices

---

## Copyright

Proprietary right of Unigraphics Solutions Inc., its subcontractors, or its suppliers are included in this software, in the data, documentation, or firmware related thereto, and in information disclosed therein. Neither this software, regardless of the form in which it exists, nor such data, information, or firmware may be used or disclosed to others for any purpose except as specifically authorized in writing by Unigraphics Solutions Inc. Recipient by accepting this document or utilizing this software agrees that neither this document nor the information disclosed herein nor any part thereof shall be reproduced or transferred to other documents or used or disclosed to others for manufacturing or any other purpose except as specifically authorized in writing by Unigraphics Solutions Inc.

©2002 Electronic Data Systems Corporation. All rights reserved.

## Restricted Rights Legend

The commercial computer software and related documentation are provided with restricted rights. Use, duplication or disclosure by the U.S. Government is subject to the protections and restrictions as set forth in the Unigraphics Solutions Inc. commercial license for the software and/or documentation as prescribed in DOD FAR 227-7202-3(a), or for Civilian Agencies, in FAR 27.404(b)(2)(i), and any successor or similar regulation, as applicable. Unigraphics Solutions Inc., 10824 Hope Street, Cypress, CA 90630.

## Warranties and Liabilities

All warranties and limitations thereof given by Unigraphics Solutions Inc. are set forth in the license agreement under which the software and/or documentation were provided. Nothing contained within or implied by the language of this document shall be considered to be a modification of such warranties.

The information and the software that are the subject of this document are subject to change without notice and should not be considered commitments by Unigraphics Solutions Inc.. Unigraphics Solutions Inc. assumes no responsibility for any errors that may be contained within this document.

The software discussed within this document is furnished under separate license agreement and is subject to use only in accordance with the licensing terms and conditions contained therein.

## Trademarks

**EDS, the EDS logo, UNIGRAPHICS SOLUTIONS®**, **UNIGRAPHICS®**, **GRIP®**, **PARASOLID®**, **UG®**, **UG/...®**, **UG SOLUTIONS®**, **iMAN®** are trademarks or registered trademarks of Electronic Data Systems Corporation or its subsidiaries. All other logos or trademarks used herein are the property of their respective owners.

## *Multi-Axis Machining Workbook* Publication History:


Original Release .....	August 2000
Version 17.1.1 .....	February 2001
Version 18.0 .....	November 2001
Unigraphics NX .....	November 2002

## The Manufacturing Process

The workbook project consists of various aspects of multi-axis machining of a part of a manufacturing assembly, in this case a turbine compressor housing. The manufacturing assembly is comprised of a fixture with associated clamping devices and the left and right hand castings of the compressor housing. The compressor housing is considered to be the *Master Model* and the fixture, with associated clamping devices, are considered component parts of the assembly.

For this project the compressor housing will be machined on a 5-axis machining center. You will center drill, drill and ream the 34 holes on the top flange of the housing and then machine the various intake manifold flanges located on the side of the housing. All tools used in the various operations have been previously defined for you.


The following illustration represents the manufacturing assembly that you will use in the NC/CNC programming process.



The manufacturing processes or methods that you will use, in this workbook, may or may not be the same approach, in order or content, that you would use at your company. The end result, the final part, is the same. What is more important, in this class, is gaining an understanding of the methodology and application of using the various Multi-axis machining options of the Manufacturing Application of Unigraphics, allowing you to customize tool path generation to methods or processes that you are familiar with.

The following flowchart illustrates the Manufacturing process steps that you will use when creating and processing tool paths in Unigraphics.

# Unigraphics Manufacturing Process



**(This Page Intentionally Left Blank)**


## Drilling the top flange

### Section 1



Prior to creating the operations that are necessary to machine the top flange, take the time to become familiar with this project part.

**Step 1** Open the part, `mam_compressor_assy_mfg.prt` from the workbook parts directory.



**Step 2** Rename the part `***_compressor_assy.prt` where `***` represents your initials.

**Step 3** Examine the assembly and the various component parts using the Assembly Navigator.

**Step 4** Enter the Manufacturing Application.



Notice that there were no previous operations or parent group, other than the defaults.

**Step 5 Change to the Tool View of the Operation Navigator.**


Note that all the tools required for the various machining operations are already defined for you.

**Step 6 Create the Machining Environment.**

The Machining Environment has already been determined for you, in this case it is multi-axis.


**Step 7 Determine the geometry and Machine Co-ordinate systems.**

Analyze the geometry needed for the various machining operations. For this project you will be drilling the holes on the top flange as well as machining the manifold flanges that are cast on the part. The manifold flanges require milling and drilling operations. Note that only one of the manifold flanges has a horizontal and vertical “t-slot”.





You will begin this project by spot-drilling, drilling and reaming 34 holes located on the top flange, as shown. Remember to specify the MCS at the center of rotation of the table since this part will be machined on a 5-axis tilt and rotating table machining center.



**Step 8 Create the operations necessary to spot-drill, drill and ream the 34 holes located on the top flange.**

Use the following tools:  
**SPOTDRILLING\_TOOL**  
**Z\_DRILL\_.413**  
**RM\_.420**

**Step 9 Use the Visualization function to verify your tool paths.**

**Step 10 Save the part file.**



**(This Page Intentionally Left Blank)**


## Sequential Mill – Cutting the Manifold flange

### Section 2

In this section, you will machine the manifold flange as shown below, using Sequential Mill operation types.

Manifold shape as cast

Manifold shape as finished




**Step 1** Continue using `***_compressor_assy_mfg.prt`.

**Step 2** Create a new program named `SEQ_MILL_PROG`.


When creating operations, use meaningful names. All operations created for Sequential Milling will use `SEQ_MILL_PROG` as the parent object.

**Step 3** Face mill top of the pad, using Sequential Milling techniques.

Face mill top of manifold




Use tool EM1.00X0 and verify your results. Your tool path should be similar to the following illustration.



2

**Step 4 Create a Sequential Milling operation to machine the outer periphery of the manifold flange.**

Use tool EM\_.500x.03 and verify your results. Your tool path should like similar to the following illustration.



**Step 5 Spot drill, and drill the Manifold flange.**


Use the following tools:

**SPOTDRILLING\_TOOL**


**DRILL\_.250**

**DRILL\_1.00**

Verify your results. Your tool path should be similar to the following illustration.



**Step 6 Create a Sequential Milling tool path to machine the dovetail slots.**



Use tool EM\_.250x.03 and verify your results. Use the looping technique of Sequential Mill to rough the dovetail slot.

**Step 7 Save and close the part file.**




**(This Page Intentionally Left Blank)**

## Variable Contour – Cutting the Manifold flange

### Section 3

In this section, you will machine the manifold flange as shown below, using Variable contour operation types. The cutting sequence will be identical to the sequence that you used in Sequential Mill. The purpose of doing this project with Sequential Mill and Variable Contour operations will allow you to compare differences between the two processors. In most multi-axis situations, you will probably use a combination of each method to machine your parts.



3


**Step 1 Continue using `***_compressor_assy_mfg.prt`.**

**Step 2 Create a new program named `VAR_CONTOUR_PROG`.**


When creating operations, use meaningful names. All operations created for Variable Contour will use `VAR_CONTOUR_PROG` as the parent object.

**Step 3 Face the top of the pad, using Variable Contouring techniques.**

Face mill top of manifold




Use tool EM1.00X0 and verify your results. Your tool path should be similar to the following illustration.



3

**Step 4 Create a Variable Contour operation to machine the outer periphery of the manifold flange.**

Use tool EM\_.500x.03 and verify your results. Your tool path should look similar to the following illustration.





**Step 5 Spot drill, and drill the Manifold flange.**


Use the following tools:

**SPOTDRILLING\_TOOL**


**DRILL\_.250**

**DRILL\_1.00**

Verify your results. Your tool path should look similar to the following illustration.



**Step 6 Create a Variable Contour tool path to machine the dovetail slots.**



Use tool EM\_.250x.03 and verify your results.

**Step 7 Save and close the part file.**

This completes the project.

(This Page Intentionally Left Blank)





