

**UNIGRAPHICS**

---

***TURNING MANUFACTURING PROCESS  
WORKBOOK***

***November 2002***

***MT11055 – Unigraphics NX***

**EDS Inc.**

---

## *Proprietary & Restricted Rights Notices*

---

### **Copyright**

Proprietary right of Unigraphics Solutions Inc., its subcontractors, or its suppliers are included in this software, in the data, documentation, or firmware related thereto, and in information disclosed therein. Neither this software, regardless of the form in which it exists, nor such data, information, or firmware may be used or disclosed to others for any purpose except as specifically authorized in writing by Unigraphics Solutions Inc. Recipient by accepting this document or utilizing this software agrees that neither this document nor the information disclosed herein nor any part thereof shall be reproduced or transferred to other documents or used or disclosed to others for manufacturing or any other purpose except as specifically authorized in writing by Unigraphics Solutions Inc.

©2002 Electronic Data Systems Corporation. All rights reserved.

### **Restricted Rights Legend**

The commercial computer software and related documentation are provided with restricted rights. Use, duplication or disclosure by the U.S. Government is subject to the protections and restrictions as set forth in the Unigraphics Solutions Inc. commercial license for the software and/or documentation as prescribed in DOD FAR 227–7202–3(a), or for Civilian Agencies, in FAR 27.404(b)(2)(i), and any successor or similar regulation, as applicable. Unigraphics Solutions Inc., 10824 Hope Street, Cypress, CA 90630.

### **Warranties and Liabilities**

All warranties and limitations thereof given by Unigraphics Solutions Inc. are set forth in the license agreement under which the software and/or documentation were provided. Nothing contained within or implied by the language of this document shall be considered to be a modification of such warranties.

The information and the software that are the subject of this document are subject to change without notice and should not be considered commitments by Unigraphics Solutions Inc.. Unigraphics Solutions Inc. assumes no responsibility for any errors that may be contained within this document.

The software discussed within this document is furnished under separate license agreement and is subject to use only in accordance with the licensing terms and conditions contained therein.

### **Trademarks**

**EDS, the EDS logo, UNIGRAPHICS SOLUTIONS®**, **UNIGRAPHICS®**, **GRIP®**, **PARASOLID®**, **UG®**, **UG/...®**, **UG SOLUTIONS®**, **iMAN®** are trademarks or registered trademarks of Electronic Data Systems Corporation or its subsidiaries. All other logos or trademarks used herein are the property of their respective owners.

### *Turning Manufacturing Process Workbook* Publication History:


Version 16.0.2.2 .....	October 2000
Version 17.0.1.1 .....	February 2001
Version 18.0 .....	January 2002
Unigraphics NX .....	September 2002

## The Manufacturing Process

The workbook project allows you to practice many of the Turning concepts that you have learned in the Student Manual.

The part that you will program is an assembly part consisting of the Piston part, blank, and components used to hold the Piston for machining. The Piston is considered the *Master Model* and the chuck, chuckface, etc. are called component parts. In the first section of the workbook, you will take a closer look at the master model, assembly components, and determine the machining sequence.

The piston assembly, is shown in the following illustration.




The manufacturing processes or methods that you will use in this workbook, may or may not be the same approach, in order or content, that you would use at your company. The importance of this project is to allow you to gain an understanding of the Turning application. You can then create programs, operations and tool paths in a way that is familiar to you and your company.

The flow chart below shows you the typical Manufacturing process when using the Unigraphics Manufacturing software. As you progress through this workbook a flow chart will be presented to show you where you are in this process.

## Unigraphics Manufacturing Process

### Turning




## Examining the Project Part


### Section 1



The piston (finished part), blank, and several components used to hold the piston for machining, are identified in the following illustration. The piston is considered the *Master Model* and the blank, chuck, chuckface and chuckjaw are called component parts.



The part geometry will be defined with a single closed part boundary.



The following process plan represents the manufacturing of the Piston. Included are the operation number, work center designation, operation description, operation name, and tool description. A definition of these items follows:

- **Operation Number** is the sequential order in which a process is performed.
- **Work Center** is the particular work area in which the operation is performed.
- **Description** is the detailed description of the operation that is to be performed.
- **Operation Name** is the actual name of the operation used to machine the specific feature or task.
- **Tool** is the description of the tool used to machine the specific feature.

Operation Number	Work Center	Description	Operation Name	Tool
		<b>Piston</b>		
<b>100.00</b>	<b>CNC Mill–Turn</b>	<b>Horizontal Mill–Turn, Side 1, Mach. No. 1450, Tape No. 12345_A</b>		
<b>100.10</b>		Rough face right end of part, leave stock	RGH_FACE	OD_80_L
<b>100.20</b>		Centerline drill to remove excess, leave stock on face	DRILL_2.750	DRILL_2.750
<b>100.30</b>		Centerline drill to remove excess material on bore face. Finish bore face	DRILL_1.00_FLT_BOT	DRILL_1.00_FLT_BOT
<b>100.40</b>		Rough OD, leave stock	RGH_OD	OD_80_L
<b>100.50</b>		Rough bore ID, leave stock	RGH_ID	ID_80_L
<b>100.53</b>		Rough bore ID left side of thread relief, leave stock	RGH_RELIEF_LEFT	ID_55_L
<b>100.57</b>		Rough bore ID right side of thread relief, leave stock	RGH_RELIEF_RIGHT	BACK-BORE_55_L
<b>100.60</b>		Finish ID front	FIN_FRT_ID	ID_55_L
<b>100.63</b>		Finish ID complete	FIN_ID	ID_55_L
<b>100.67</b>		Finish right side of relief	FIN_RELIEF_RIGHT	BACK-BORE_35_L
<b>100.70</b>		Finish OD	FIN_OD	OD_55_L
<b>100.80</b>		Finish groove	FIN_GRV	OD_GROOVE_L
<b>100.90</b>		Thread ID	THRD_ID	ID_THREAD_L
<b>200</b>		Mill 8 slots X .500” wide (vertical machining center)	MILL_SLOTS	EM_500_CAR-BIDE
<b>300</b>		<b>Horizontal Mill–Turn, Side 2, Mach. No. 1450, Tape No. 12345_B</b>		
<b>300.10</b>		Rough & finish face		
<b>300.20</b>		Rough OD		
<b>300.30</b>		Drill 1/8” hole on center		
<b>300.40</b>		Finish OD		



**Examining the Project Part**

---

**1**

<b>Operation Number</b>	<b>Work Center</b>	<b>Description</b>	<b>Operation Name</b>	<b>Tool</b>
<b>300.50</b>		Finish groove		
<b>300.60</b>		Finish thread		
<b>400</b>	<b>Inspection</b>	<b>Inspect 1st article features machined in operation numbers 100 thru 1010</b>		
<b>500</b>	<b>Manual Deburr Clean</b>	<b>deburr and clean part per customer specifications</b>		
<b>600</b>	<b>Inspection</b>	<b>Final inspection of all features</b>		




# Machining Environment and Creating Lathe Cross Sections

## Section 2


### Unigraphics Manufacturing Process

#### Turning



Before you start to create operations and generate tool paths, the Machining Environment must be defined. You must also create cross sections of the solid model in order to obtain the 2D geometry needed to create and generate operations.

Piston, Right side, in the chuck assembly



**Step 1** Open the part, **tmp\_piston\_mfg\_asmb\_1.prt**, from the workbook\_parts directory.

**Step 2** Rename the part **\*\*\*\_piston\_mfg\_asmb\_1**.

**Step 3** Choose the CAM Session Configuration and Setup, and then initialize the part file.

**The “Why”** Remember, the Configuration and Setup determine which templates and libraries are loaded into this part when you perform the initialization.


**HINT** Does the part require any Milling?

**Step 4** Examine the layer settings.

**Step 5** Make the layers containing the chuck and chuckjaw invisible so that only the part and the blank are visible.


**Step 6** Create the cross section curves of the Blank on their own layer.

**HINT** You might also change the display to wireframe in order to see the blank.




**Step 7** Create the cross section curves of the piston on the same layer as the cross section curves of the blank.

**HINT** Dismiss the blank and blank cross section layers and change the display to **Hidden Edges**→**Invisible**. Also, make the layers with the cross sections visible and all other layers invisible.




**HINT** The geometry on the right end of the piston is not symmetrical. It will require that you use the Complex cross section method.

**HINT** When creating the Section plane you can use the three points method. Use the arc centers for two of the points and use a control point of one of the arcs on the face of the part for the third point.



**Step 8** Make the layers containing solid geometry invisible and change the layout to the Top view.




**Step 9** Save the part file.



**(This Page Intentionally Left Blank)**

*Defining Tools and Geometry*  
Section 3

**Unigraphics Manufacturing Process**  
**Turning**



3

In this section of the workbook, you will define the tools and geometry necessary to create the operations to cut this part.

**The “Why”** Predefining the tools and geometry allows you to create operations and tool paths more efficiently.

**Step 1** If necessary, open the part from the workbook\_parts directory, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create the tools necessary to cut the part.

- The tools are identified in the Process Planning Sheet. To save time a list has been created for you. Create the following tools.

- Turning tools:

**OD\_80\_L:**  
Nose Radius .031  
Orient Angle 5.00  
Tool Number 1  
Adjust Number 1

**OD\_55\_L:**  
Nose Radius .031  
Orient Angle 17.5  
Tool Number 2  
Adjust Number 2

**ID\_80\_L:**  
Nose Radius .031  
Orient Angle 275  
Tool Number 3  
Adjust Number 3

**ID\_55\_L:**  
Nose Radius .031  
Orient Angle 282.5  
Tool Number 4  
Adjust Number 4

**ID\_35\_L:**  
Nose Radius .0312  
Orient Angle 285  
Tool Number 5  
Adjust Number 5





**BACKBORE\_55\_L:**

**Nose Radius** .0468  
**Orient Angle** 212.5  
**Tool Number** 6  
**Adjust Number** 6

**BACKBORE\_35\_L:**

**Nose Radius** .0468  
**Orient Angle** 227.5  
**Tool Number** 7  
**Adjust Number** 7

**ROUND (start with OD\_80\_L tool / change the insert type):**

**Diameter** .162  
**Holder Width** .162  
**Orient Angle** 90

- Drilling tools:

**DRILL\_2.75 (Drilling Tool):**

**Diameter** 2.75  
**Length** 20.00  
**Point Angle** 118  
**Tool Number** 8  
**Adjust Number** 8



**DRILL\_1.00FLT\_BOT (Drilling Tool):**

**Diameter** 1.00  
**Length** 20.00  
**Point Angle** 180  
**Tool Number** 9  
**Adjust Number** 9

- Grooving tools:

**OD\_GROOVE\_L:**

**Insert Width** .250  
**Radius** .016  
**Tool Number** 10  
**Adjust Number** 10


- Threading tools:

**ID\_THREAD\_L:**  
**Left Angle**            30  
**Right Angle**         30  
**Orient Angle**        270.00  
**Tool Number**        11  
**Adjust Number**      11

**Step 3** Create the boundaries in the existing WORKPIECE object. Select Aluminum for the Part Material.


- Verify that the MCS\_SPINDLE Parent Group is defined correctly.
- The WORKPIECE object should already be created under the MCS\_SPINDLE Parent Group (in order to inherit the MCS coordinates).

3



- Create an open Blank Boundary in the existing WORKPIECE object.

**Step 4** Create a closed Part boundary in the existing WORKPIECE object.



**Step 5** Save the part file.




**(This Page Intentionally Left Blank)**



# Facing Operation


## Section 4

### Unigraphics Manufacturing Process Turning



There are eight different roughing and three different finishing operation subtypes in Turning. Each operation subtype represents a different method of material removal. Selection of the operation subtype is normally based on cutting tool availability, machine rigidity, type of material being cut, geometry or feature configuration, speeds and feeds and desired finish.

In this section of the workbook, you will use one of the roughing subtypes (Facing) to face the right front of the piston.



Remember that when you are creating these operations, common options such as engage and retract parameters, avoidance parameters, containment, and feeds and speeds may need to be specified.

4

**Step 1** If necessary, open the part, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create an operation to rough face the right of the blank using the **OD\_80\_L** tool (name the operation **RGH\_FACE**).

**HINT** Remember to define the Program, Tool, Method and Geometry Parent Groups for the operation.

Choose **WORKPIECE** as the geometry Parent Group.


- Set the Containment options and then display the containment area.
- Turn off the Cleanup option. You do not need to make the additional pass to cleanup step material left from previous passes.

**Step 3** Add Start and Return points to the operation.

**HINT** The system will move from the last tool position in the previous tool path to the first GOTO of the next tool path. In some cases this can cause the tool to gouge the part.


Face Operation

+ Start/ Return



**Step 4** Generate and verify the tool path.

Your tool path should look similar to the tool path shown.



**Step 5** Save the part.


**(This Page Intentionally Left Blank)**





*Drilling to Rough the ID*  
Section 5

**Unigraphics Manufacturing Process**  
**Turning**




## Drilling to Rough the ID

---


In this section, you will rough the ID of the piston using two drilling operations. The first operation will use the DRILL\_2.750 to cut to the bottom of the hole. The second operation will use the flat bottom drill to clear material left by the drill tip. This will allow the ID turning tool (used later) to cut without gouging.

The results of the two operations should look similar to the results shown below.



**Step 1** If necessary, open the part, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create a CENTERLINE\_DRILLING operation, named DRILL\_2.750, to drill to the bottom ID of the piston using the DRILL\_2.750 tool.



**HINT** Remember to define the Program, Tool, Method and Geometry Parent Groups for the operation. Choose WORKPIECE as the Geometry Parent Group.

**HINT** When selecting the Method Parent Group, remember that this is a drilling operation.


**HINT** Remember to define the Avoidance Geometry.

Define the Drilling Geometry.

**Step 3** Generate and verify the tool path.

Your tool path should look similar to the tool path shown.

**Step 4** Create a CENTERLINE\_DRILLING operation, named DRILL\_1.00\_FLT\_BOT, to drill to the bottom ID of the piston using the DRILL\_1.00\_FLT\_BOT tool.




- Define the Drilling Geometry.
- Define the Avoidance Geometry.

**Step 5** Add a Return point on the centerline so the tool clears the part.

**Step 6** Generate and verify the tool path.

Your tool path should look similar to the tool path shown.





**Step 7** Save the part.


**(This Page Intentionally Left Blank)**



*Roughing the OD*  
Section 6




**Unigraphics Manufacturing Process**  
**Turning**




In this section of the workbook, you will use ROUGH\_TURN\_OD to machine the right end of the piston.

6



**Step 1** If necessary, open the part from the workbook\_parts directory, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create a ROUGH\_TURN\_OD operation, named RGH\_OD, using the OD\_80\_L tool to cut the geometry as shown.



**HINT** Remember to define the Program, Tool, Method and Geometry Parent Groups for the operation. Choose WORKPIECE as the Geometry Parent Group.


- Define an appropriate Cut depth.
- Set the Containment options and then display the containment area.



- Add Start and Return Points.
- Remember to select Reversal Mode, Omit.

**Step 3** Generate and verify the tool path.

Your tool path should look similar to the tool path shown.




**Step 4** Save the part.



**(This Page Intentionally Left Blank)**


*Roughing the ID*  
Section 7

**Unigraphics Manufacturing Process**  
**Turning**




In this section of the workbook, you will use ROUGH\_BORE\_ID to machine the ID of the piston.

7




**Step 1** If necessary, open the part, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create a roughing operation called **RGH\_ID**, using the **ID\_80\_L** tool to cut the geometry as shown.



**HINT**

Some of the options you may want to set are: Reversal Mode, Cut Depth, and Avoidance moves.




+ Return

+ Start


**Step 3** Generate the tool path.

Your tool path should look similar to the tool path shown.



**Step 4** You are going to create two operations to remove the material in the undercut region.

- Use **Workpiece**→**Show 2D** to verify the geometry to be cut.



**Step 5** Create a roughing operation using the ID\_55\_L tool to cut the geometry as shown in the undercut (name the operation RGH\_RELIEF\_LEFT.).

- The Cleanup options should be set to Down Only.

**Step 6** Create a second roughing operation using the ID\_35\_L tool to cut the remaining geometry in the undercut (name the operation RGH\_RELIEF\_RIGHT.).

**Step 7** Save the part.




**(This Page Intentionally Left Blank)**

*Finishing the ID and OD*  
Section 8


**Unigraphics Manufacturing Process**

**Turning**



In this section, you will finish turning the ID and OD of the piston.

You will create three operations to finish the ID. The first and second operations will cut the geometry as shown in the following illustration.



**Step 1** If necessary, open the part, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create an **FINISH\_BORE\_ID** operation, called **FIN\_FRT\_ID**, to finish the front of the ID using the **ID\_55\_L** tool.

- Set a Start Point only for the first operation.

**HINT**

Check your Fillets setting, you may want to adjust this option.

- Generate the tool path.


**Step 3** Create another **FINISH\_BORE\_ID** operation, called **FIN\_ID**, to finish the rest of the ID using the **ID\_55\_L** tool.

- Set a Return Point only for the second operation.
- Generate the tool path.






Your tool paths should look similar to the tool paths shown.




**Step 4** Create a FINISH\_BACK\_BORE, called FIN\_RELIEF\_RIGHT, operation to finish the remaining portion of the ID using the BACKBORE\_35\_L tool.



Add Start and Return Points.


**Step 5** Generate the tool path.

Your tool paths should look similar to the tool paths shown.



In this section, you will finish the OD of the piston.

**Step 6** Create an operation to finish the OD, called FIN\_OD, using the OD\_55\_L tool as shown.




- Set the Containment using Trim Points.

**HINT** Remember how to set Engage and Retract settings to control the engage and retract behavior at the Trim Points.

**HINT** Remember the Omit Reversals option.

- Add Start and Return Points.

**Step 7** Generate the tool path.  
Your tool path should look similar to the tool path shown.




**Step 8** Save the part.

# Cutting the Groove


Section 9

## Unigraphics Manufacturing Process

### Turning



You will use the Groove operation type to finish the grooved portion of the Piston OD.



**Step 1** If necessary, open the part, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create an operation to finish the groove, called **FIN\_GRV**, using the **OD\_GROOVE\_L** tool.

- Use the Down Only Cut Pattern.
- Add Start and Return points.


**HINT** Pay special attention to the motion you use to the Return Point.

- Modify the Retract Move (Level/Part).
- Define the Stepover (50%).

**Step 3** Generate the grooving operation.

**Step 4** Use the **Workpiece**→**Show 2D** to verify the cut.

Your tool path should look similar to the tool path shown.




**Step 5** Save the part.

**(This Page Intentionally Left Blank)**




*Teach Mode – Finish ID*  
 Section 10


**Unigraphics Manufacturing Process**  
**Turning**



You will use the Teach Mode operation type to finish the front portion of the Piston ID.



You will then create a second operation to finish cut the ID as shown in the following illustration.





In this section, you are going to use a different part file to create the following operations. In your original part file, you have already finished this bore using the FINISH\_BORE\_ID and FINISH\_BACK\_BORE operation types. Later you will return to the original part file, **\*\*\*\_piston\_mfg\_asmb\_1.prt**, and finish the programming. The new part, which looks the same as the original part, is used to show that you can finish this ID using a different operation type and to give you practice using Teach Mode.

**Step 1** Open the part from the workbook\_parts directory, **tmp\_piston\_mfg\_teach.prt**.


**Step 2** Rename the part **\*\*\*\_mfg\_piston\_teach**.

**Step 3** Create a Teach Mode operation to cut the front portion of the part using ID for the geometry parent group and BACK\_BORE\_35\_L for the tool.

Use the Auto Engage and Retract moves.

Create two sub-operations.

Create the first Follow Curve Motion to cut the backside of the first large radius as shown.




**HINT** Remember to select the material side in Follow Curve Motion before selecting the curves.

**HINT** The first motion sub-operation will use end points to define the cut geometry.


**HINT** The direction the ID geometry that was originally selected determines the cut direction.

Create the second Follow Curve Motion to cut the flat towards the front face as shown.




**HINT** The second cut motion sub-operation will require an offset from the start point. The Along Curve offset method works well.

Your tool path should look similar to the tool path shown.




**Step 4** Create a second Teach Mode operation to finish the remaining portion of the ID using the ID\_55\_L tool.

**HINT** This operation requires at least 3 tool motion sub-operations, each using points for the start and end geometry. The first Follow Curve Motion is shown below.



Your tool path should look similar to the tool path shown.



**Step 5** Save the part.

**(This Page Intentionally Left Blank)**




# Cutting Threads

Section 11


## Unigraphics Manufacturing Process

### Turning



In this section, you are going to cut threads on the ID of the part as shown in the following illustration.

11



Remember, when you are creating these operations, common options, such as engage and retract parameters, and feeds and speeds must be specified.

You will now return to the part file that you were working with in a previous session.

**Step 1** Open the part, **\*\*\*\_piston\_mfg\_asmb\_1.prt**.

**Step 2** Create an operation to thread the ID on the right end of the part, called **THRD\_ID**, using the **ID\_THREAD\_L** tool.

**HINT** Remember to define the Program, Tool, Method and Geometry Parent Groups for the operation.

**Step 3** Define the Thread Geometry.

**HINT** The crest line is the outside of the thread.

**Step 4** Define the Pitch.

**HINT** This determines the threads per inch.

**Step 5** Define the Total Depth the tool will cut (Depth & Angle; .225 depth & 180 deg).


- Make sure to define the Increment setting.

**HINT** Remember, the increment defines how the tool will move from the crest line to the root line.

**Step 6** Define an Offset for the Start and End of the Thread.

**Step 7** Specify Finish and Chase Passes.

Your tool path should look similar to the tool path shown below.



**Step 8** Save the part.



**(This Page Intentionally Left Blank)**





